

COUNTY OF LOS ANGELES
DEPARTMENT OF PUBLIC WORKS
BUILDING AND SAFETY DIVISION

INVESTIGATION REPORT

LOCATION OF PROBLEM

2947 Grand St.

LOCALITY

Walnut park

DESCRIPTION OF PROBLEM

Chimney ~~needs~~ needs
inspection due to shifting due
to Earthquake.

REQUESTED BY

Wiertzema
Rod ~~Wiertzema~~

PHONE 310-839-0918

ADDRESS

4534 Johnson Ave.
Calver City

213) 560-3123

RECEIVED BY

Mechelle Samuel

DATE

5/17/95

REFERRED TO

Rodgers

DATE

5/21/95

REPORT OF INVESTIGATION

INVESTIGATOR

TITLE

DATE

COPY SENT TO

TITLE

DATE

REPORT FLOWED TO

TITLE

DATE